


序号	报告编号	发布日期	结论	影像资料
12	GX-B1371/21-9-24038	2024. 11. 20	<p>存在问题：</p> <ol style="list-style-type: none"> 1、中心站无声光报警装置。 2、双机备份及切换功能不正常。 3、风速传感器报警值未根据安装地点进行设置。 4、无规章制度。 5、监测监控设备未定期进行调校。 6、无台账及报表。 7、监测监控系统布置图中未标明中心站的位置，以及供电电缆的走向。 <p>建议：加强传感器日常维护及调校。</p> <p>除上述问题外，其余所检项目合格。</p>	
13	GX-B1371/21-9-24039	2024. 11. 20	<p>存在问题：</p> <ol style="list-style-type: none"> 1、中心站无声光报警装置。 2、双机备份及切换功能不正常。 3、风速传感器报警值未根据安装地点进行设置。 4、无规章制度。 5、监测监控设备未定期进行调校。 6、无台账及报表。 7、监测监控系统布置图中未标明中心站、分站等设备的位置，以及信号线缆和供电电缆走向等。 <p>建议：加强传感器日常维护及调校。</p> <p>除上述问题外，其余所检项目合格。</p>	

14	GX-B1346/21-9-24006	2024.11.22	低瓦斯矿井	
15	GX-B1346/21-9-24004	2024.11.25	低瓦斯矿井	
16	GX-B1340/23-9-24064	2024.11.22	西风井1#主要通风机系统合格。	 A photograph showing a large, orange industrial fan system, likely a main fan system for a mine. The fan is mounted on a concrete base and has a large, curved, orange metal housing. Two workers in blue and black uniforms and red hard hats are standing next to the fan, providing a sense of scale. The fan has Chinese text on it, including '卧龙电气南阳防爆集团股份有限公司' (Wolong Electrical Nanyang Explosion-proof Group Co., Ltd.) and '地面用防爆抽出式对旋轴流风机' (Explosion-proof抽出式对旋轴流风机 for ground use). The date '2024-10-11' is visible in the bottom right corner of the image.

17	GX-B1340/23-9-24065	2024.11.22	西风井2#主要通风机系统合格。	
----	---------------------	------------	-----------------	---