




序号	报告编号	发布日期	结论	影像资料
69	GX-B1313/21-2-25017~25025	2025/3/14	本次共检电力变压器9台，9台所检项目合格。	
70	GX-B1322/21-2-25022~25028	2025/3/14	本次共检电力电缆7条，7条所检项目合格。	

71	GX-B1310/21-2-25030	2025. 3. 13	符合标准要求。	 <p>2025/02/24</p>
72	GX-B1310/21-2-25031	2025. 3. 13	符合标准要求。	 <p>2025/02/24</p>
73	GX-B1310/21-2-25032	2025. 3. 14	符合标准要求。	 <p>2025/02/26</p>

74	GX-B1427/21-2-25032	2025. 3. 14	符合标准要求。	
75	GX-B1310/21-2-25033	2025. 3. 14	符合标准要求。	
76	GX-B1427/21-2-25033	2025. 3. 14	符合标准要求。	

77	GX-B1328/20-2-25024	2025. 3. 15	合格	
78	GX-B1328/20-2-25025	2025. 3. 15	合格	
79	GX-B1328/20-2-25026	2025. 3. 15	合格	

80	GX-B1328/20-2-25027	2025. 3. 15	合格	
81	GX-B1328/20-2-25028	2025. 3. 15	合格	
82	GX-B1350/21-2-25005	2025. 3. 15	所检项目合格	

83	GX-B1328/20-2-25029	2025. 3. 17	合格	
84	GX-B1500/21-2-25008	2025. 3. 17	综合判定：合格。	
85	GX-B1500/21-2-25009	2025. 3. 17	综合判定：合格。	

86	GX-B1500/21-2-25010	2025. 3. 17	综合判定：合格。	
87	GX-B1500/21-2-25011	2025. 3. 17	综合判定：合格。	
88	GX-B1500/21-2-25012	2025. 3. 17	综合判定：合格。	




89	GX-B1500/21-2-25013	2025. 3. 17	综合判定：合格。	
90	GX-B1500/21-2-25014	2025. 3. 17	综合判定：合格。	
91	GX-B1500/21-2-25015	2025. 3. 17	综合判定：合格。	






92	GX-B1500/21-2-25016	2025. 3. 17	综合判定：合格。	 2025/03/08
93	GX-B1500/21-2-25017	2025. 3. 17	综合判定：合格。	 2025/03/08
94	GX-B1500/21-2-25018	2025. 3. 17	综合判定：合格。	 2025/03/08

95	GX-B1500/21-2-25019	2025. 3. 17	综合判定：合格。	 <p>2025.03.08</p>
96	GX-B1500/21-2-25020	2025. 3. 17	综合判定：合格。	 <p>2025.03.08</p>
97	GX-B1309/21-2-25003	2025. 3. 17	所检项目合格。	 <p>2025.03.08</p>

98	GX-B1309/21-2-25004	2025. 3. 17	所检项目合格。		
99	GX-B1621/24-2-25001	2025. 3. 17	实测流量116.5m <sup>3</sup> /h， 不作判定，其余所检项目合格。		
100	GX-B1621/24-2-25002	2025. 3. 17	实测流量128.1m <sup>3</sup> /h， 不作判定，其余所检项目合格。		

101	GX-B1621/24-2-25003	2025. 3. 17	实测流量115.7m <sup>3</sup> /h， 不作判定，其余所检项目合格。	
102	GX-B1322/21-2-25001~25006	2025. 3. 17	本次共检验电力电缆6 条，6条所检项目合格 。	
103	GX-B1329/21-2-25057~25064	2025. 3. 17	本次共检氧化锌避雷器 8组，8组所检项目合格 。	

104	GX-B1313/21-2-25001~25004	2025. 3. 17	本次共检电力变压器4台，4台所检项目合格。 。	 A photograph showing two workers in red hard hats and dark clothing inspecting a large industrial power transformer. One worker is standing and looking towards the camera, while the other is partially visible behind him. The transformer is a large, grey metal cabinet with various components on top. A date stamp '2025.3.4' is visible in the bottom right corner of the photo.
105	GX-B1324/21-2-25001	2025. 3. 17	本次共检验三相交流电动机1台，1台三相交流电动机所检项目合格。	 A photograph of a worker in a red hard hat and grey work clothes inspecting a three-phase AC motor. The worker is standing next to a yellow safety railing. A blue toolbox is open on the floor in the foreground. The date stamp '2025.3.4' is visible in the bottom right corner of the photo.
106	GX-B1451/20-2-25001~25006	2025. 3. 17	本次共检高压开关柜6台，6台所检项目合格。 。	 A photograph showing two workers in red hard hats inspecting high-voltage switchgear. One worker is standing on a small step ladder, reaching up to inspect a component of the switchgear. The other worker is kneeling on the floor, looking at a tablet or device. The date stamp '2025.3.4' is visible in the bottom right corner of the photo.

107	GX-B1322/21-2-255039-25044	2025. 3. 18	本次共检验电力电缆6条，6条所检项目合格。 。	
108	GX-B1451/20-2-25125~25128	2025. 3. 18	本次共检高压开关柜4台，4台所检项目合格。 。	
109	GX-B1313/21-2-25051~25052	2025. 3. 18	本次共检电力变压器2台，2台所检项目合格。 。	



110	GX-B1313/21-2-25053~25054	2025. 3. 18	本次共检电力变压器2台，2台所检项目合格。 。	
111	GX-B1329/21-2-25102~25107	2025. 3. 18	本次共检氧化锌避雷器6组，6组所检项目合格。 。	
112	GX-B1310/21-2-25020	2025. 3. 18	符合标准要求	






113	GX-B1310/21-2-25021	2025. 3. 18	符合标准要求	 <p>2025/02/24</p>
114	GX-B1310/21-2-25022	2025. 3. 18	符合标准要求	 <p>2025/02/24</p>
115	GX-B1310/21-2-25023	2025. 3. 18	符合标准要求	 <p>2025/02/24</p>

116	GX-B1310/21-2-25024	2025. 3. 18	符合标准要求	 2025/02/24
117	GX-B1310/21-2-25025	2025. 3. 18	符合标准要求	 2025/02/24
118	GX-B1310/21-2-25026	2025. 3. 18	符合标准要求	 2025/02/24

119	GX-B1310/21-2-25027	2025. 3. 18	符合标准要求	 <p>2025/02/24</p>
120	GX-B1310/21-2-25028	2025. 3. 18	符合标准要求	 <p>2025/02/24</p>
121	GX-B1310/21-2-25029	2025. 3. 18	符合标准要求	 <p>2025/02/24</p>

122	GX-B1310/21-2-25043	2025. 3. 18	符合标准要求	
123	GX-B1310/21-2-25044	2025. 3. 18	符合标准要求	
124	GX-B1310/21-2-25045	2025. 3. 18	符合标准要求	




125	GX-B1313/21-2-25026~25028	2025/3/17	本次共检电力变压器3台，3台所检项目合格。 。	
126	GX-B1313/21-2-25029~25031	2025/3/17	本次共检电力变压器3台，3台所检项目合格。 。	
127	GX-B1313/21-2-25043~25047	2025/3/17	本次共检电力变压器5台，5台所检项目合格。 。	

128	GX-B1313/21-2-25048~25050	2025/3/17	本次共检电力变压器3台，3台所检项目合格。 。	 A photograph showing three large power transformers in an outdoor substation. Several workers in safety gear are visible around the transformers. The date stamp in the bottom right corner of the image is 2025/03/01.
129	GX-B1322/21-2-25029~25031	2025/3/17	本次共检电力电缆3条，3条所检项目合格。 。	 A photograph of a worker in a red hard hat and safety gear kneeling on the ground in a substation, inspecting a power cable. The date stamp in the bottom right corner of the image is 2025/2/28.
130	GX-B1322/21-2-25032~25034	2025/3/17	本次共检电力电缆3条，3条所检项目合格。 。	 A photograph showing several workers in safety gear inspecting power cables in a substation. One worker is kneeling on a green mat, while others stand nearby. The date stamp in the bottom right corner of the image is 2025/3/1.







131	GX-B1350/21-2-25006	2025/3/17	<p>本次共检接地装置 8处，8处接地装置所检 项目合格。</p>	
132	GX-B1598/24-2-25032	2025. 3. 20	<p>实测钢丝绳有效截面积 损失百分比最大为 1.67%，小于5%为正常 。</p>	
133	GX-B1598/24-2-25033	2025. 3. 20	<p>实测钢丝绳有效截面积 损失百分比最大为 1.78%，小于5%为正常 。</p>	



134	GX-B1598/24-2-25034	2025. 3. 20	实测钢丝绳有效截面积损失百分比最大为1.74%，小于5%为正常。	
135	GX-B1598/24-2-25035	2025. 3. 20	实测钢丝绳有效截面积损失百分比最大为1.52%，小于5%为正常。	
136	GX-B1598/24-2-25036	2025. 3. 20	实测钢丝绳有效截面积损失百分比最大为1.67%，小于5%为正常。	

137	GX-B1598/24-2-25037	2025. 3. 20	实测钢丝绳有效截面积 损失百分比最大为 1.73%，小于5%为正常 。	
138	GX-B1598/24-2-25038	2025. 3. 20	实测钢丝绳有效截面积 损失百分比最大为 2.49%，小于5%为正常 。	
139	GX-B1598/24-2-25039	2025. 3. 20	实测钢丝绳有效截面积 损失百分比最大为 2.57%，小于5%为正常 。	

140	GX-B1598/24-2-25040	2025. 3. 20	实测钢丝绳有效截面积 损失百分比最大为 2.76%，小于5%为正常 。	
141	GX-B1598/24-2-25041	2025. 3. 20	实测钢丝绳有效截面积 损失百分比最大为 1.29%，小于5%为正常 。	
142	GX-B1598/24-2-25042	2025. 3. 20	实测钢丝绳有效截面积 损失百分比最大为 0.99%，小于5%为正常 。	

143	GX-B1598/24-2-25043	2025. 3. 20	实测钢丝绳有效截面积 损失百分比最大为 1.17%，小于5%为正常 。	
144	GX-B1598/24-2-25044	2025. 3. 20	实测钢丝绳有效截面积 损失百分比最大为 1.35%，小于5%为正常 。	