


序号	报告编号	发布日期	结论	影像资料
13	GX-B1346/21-8-24006	2024. 11. 19	低瓦斯矿井	
14	GX-B1341/24-8-24060	2024. 11. 25	综合判断：合格	

15	GX-B1343/21-8-24024	2024. 11. 25	矿井通风阻力：主通风系统752.0Pa。	 A worker in a red uniform and helmet is inspecting a tunnel. The worker is holding a device and looking at the tunnel wall. The tunnel is dimly lit with a headlamp. The date 2024-11-22 is visible in the bottom right corner of the image.
16	GX-B1347/21-8-24024	2024. 11. 25	综合指标：90.2%，大于72%，合格。	 A worker in a red uniform and helmet is inspecting a tunnel. The worker is holding a device and looking at the tunnel wall. The tunnel is dimly lit with a headlamp. There are pipes and equipment visible in the background. The date 2024-11-22 is visible in the bottom right corner of the image.