


序号	报告编号	发布日期	结论	影像资料
179	GX-B1362/23-A-25049	2025/2/19	所检项目合格	
180	GX-B1362/23-A-25050	2025/2/19	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
181	GX-B1362/23-A-25051	2025/2/19	所检项目合格	
182	GX-B1361/22-A-25153	2025/2/19	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
183	GX-B1361/22-A-25154	2025/2/19	所检项目合格	
184	GX-B1361/22-A-25155	2025/2/19	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
185	GX-B1361/22-A-25156	2025/2/19	所检项目合格	
186	GX-B1361/22-A-25157	2025/2/19	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
187	GX-B1361/22-A-25158	2025/2/19	所检项目合格	
188	GX-B1361/22-A-25164	2025/2/19	所检项目合格	



序号	报告编号	发布日期	结论	影像资料
189	GX-B1361/22-A-25165	2025/2/19	所检项目合格	
190	GX-B1361/22-A-25166	2025/2/19	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
191	GX-B1361/22-A-25177	2025/2/19	合格	
192	GX-B1361/22-A-25178	2025/2/19	合格	

序号	报告编号	发布日期	结论	影像资料
193	GX-B1362/23-A-25052	2025/2/21	合格	
194	GX-B1361/22-A-25196	2025/2/21	不合格	


序号	报告编号	发布日期	结论	影像资料
195	GX-B1361/22-A-25167	2025/2/21	所检项目合格	
196	GX-B1361/22-A-25168	2025/2/21	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
197	GX-B1361/22-A-25169	2025/2/21	所检项目合格	
198	GX-B1361/22-A-25170	2025/2/21	所检项目合格	



序号	报告编号	发布日期	结论	影像资料
199	GX-B1361/22-A-25171	2025/2/21	所检项目合格	
200	GX-B1361/22-A-25172	2025/2/21	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
201	GX-B1361/22-A-25175	2025/2/21	所检项目合格	
202	GX-B1361/22-A-25176	2025/2/21	所检项目合格	



序号	报告编号	发布日期	结论	影像资料
203	GX-B1361/22-A-25192	2025/2/21	合格	
204	GX-B1361/22-A-25193	2025/2/21	合格	

序号	报告编号	发布日期	结论	影像资料
205	GX-B1361/22-A-25194	2025/2/21	合格	
206	GX-B1361/22-A-25195	2025/2/21	合格	



序号	报告编号	发布日期	结论	影像资料
207	GX-B1361/22-A-25173	2025/2/20	所检项目合格	
208	GX-B1361/22-A-25174	2025/2/20	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
209	GX-B1362/23-A-25055	2025/2/26	所检项目合格	 A photograph showing two workers in grey work uniforms operating a large industrial machine in a workshop. The machine is processing a long, narrow object, possibly a mold or a component. A yellow timestamp '2025/2/23' is visible in the bottom right corner of the image.
210	GX-B1362/23-A-25056	2025/2/26	所检项目合格	 A photograph showing two workers in grey work uniforms operating a large industrial machine in a workshop. The machine is processing a long, narrow object, possibly a mold or a component. A yellow timestamp '2025/2/23' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
211	GX-B1362/23-A-25057	2025/2/26	所检项目合格	
212	GX-B1362/23-A-25053	2025/2/26	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
213	GX-B1362/23-A-25054	2025/2/26	所检项目合格	
214	GX-B1361/22-A-25197	2025/2/26	所检项目合格	


序号	报告编号	发布日期	结论	影像资料
215	GX-B1361/22-A-25198	2025/2/26	所检项目合格	
216	GX-B1361/22-A-25199	2025/2/26	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
217	GX-B1361/22-A-25200	2025/2/26	所检项目合格	
218	GX-B1361/22-A-25179	2025/2/27	不合格	

序号	报告编号	发布日期	结论	影像资料
219	GX-B1361/22-A-25180	2025/2/27	所检项目合格	
220	GX-B1361/22-A-25181	2025/2/27	不合格	

序号	报告编号	发布日期	结论	影像资料
221	GX-B1361/22-A-25182	2025/2/27	不合格	
222	GX-B1361/22-A-25183	2025/2/27	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
223	GX-B1361/22-A-25184	2025/2/27	所检项目合格	
224	GX-B1361/22-A-25185	2025/2/27	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
225	GX-B1361/22-A-25186	2025/2/27	所检项目合格	
226	GX-B1361/22-A-25187	2025/2/27	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
227	GX-B1361/22-A-25188	2025/2/27	所检项目合格	
228	GX-B1361/22-A-25189	2025/2/27	所检项目合格	



序号	报告编号	发布日期	结论	影像资料
229	GX-B1361/22-A-25190	2025/2/27	所检项目合格	
230	GX-B1361/22-A-25201	2025/2/28	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
231	GX-B1361/22-A-25202	2025/2/28	所检项目合格	 A photograph showing two workers in a laboratory or workshop. One worker is operating a large piece of machinery, possibly a lathe or mill, while the other worker stands nearby, handling a long, cylindrical object. The date '2025/2/24' is visible in the bottom right corner of the image.
232	GX-B1361/22-A-25203	2025/2/28	所检项目合格	 A photograph showing a worker in a laboratory or workshop, focused on operating a piece of machinery. The worker is wearing a light-colored jacket and is using a tool to work on a component. The date '2025/2/24' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
233	GX-B1361/22-A-25204	2025/2/28	所检项目合格	
234	GX-B1361/22-A-25205	2025/2/28	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
235	GX-B1361/22-A-25206	2025/2/28	所检项目合格	
236	GX-B1361/22-A-25207	2025/2/28	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
237	GX-B1361/22-A-25208	2025/2/28	所检项目合格	
238	GX-B1361/22-A-25209	2025/2/28	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
239	GX-B1361/22-A-25210	2025/2/28	所检项目合格	
240	GX-B1361/22-A-25211	2025/2/28	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
241	GX-B1361/22-A-25212	2025/2/28	所检项目合格	
242	GX-B1361/22-A-25213	2025/2/28	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
243	GX-B1361/22-A-25214	2025/2/28	所检项目合格	
244	GX-B1361/22-A-25215	2025/2/28	合格	

序号	报告编号	发布日期	结论	影像资料
245	GX-B1361/22-A-25216	2025/2/28	合格	
246	GX-B1361/22-A-25217	2025/2/28	合格	

序号	报告编号	发布日期	结论	影像资料
247	GX-B1361/22-A-25235	2025/2/28	所检项目合格	